

Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/05/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering


CNC Civil Services

Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|---|
| Test Hole Number: 1 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Excavation Crew: KB AB DF | |
| Utility Requested: Steam | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Steam | |
| Utility Material: Wrapped Steel | |
| Utility Color: Black | |
| Nominal Utility Size: 12" | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 12.5" | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input checked="" type="checkbox"/> N/A <input type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|--|
| Cover (Top) | Test Hole Profile Sketch: |
| 4.89' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NE | |
| Marker Set | |
| PK <input type="checkbox"/> | Test Hole Survey Information: Field Surveyed By: CNC Civil Services Survey Control Established By: AMT Engineering Survey Coordinates: Northing: 687733.27 Easting: 1575727.44 Elevation: 37.55 Elevation Data: Marker: 37.55' Utility Top: 32.66' Utility Bottom: N/A Test Hole Notes: Hub and tack set over crown of the utility. _____ _____ _____ |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: 1

PERRY POINT

Project Name: TEST HOLES

Project Number: MD23-045

Project Client: AMT

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/05/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering


CNC Civil Services

Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|---|
| Test Hole Number: 1A | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Excavation Crew: KB AB DF | |
| Utility Requested: Gas | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Gas | |
| Utility Material: Wrapped Steel | |
| Utility Color: Yellow | |
| Nominal Utility Size: 2" | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 2.5" | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 2.60' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| E | |
| Marker Set | |
| PK <input type="checkbox"/> | Test Hole Survey Information: Field Surveyed By: CNC Civil Services Survey Control Established By: AMT Engineering Survey Coordinates: Northing: 687733.84 Easting: 1575726.07 Elevation: 37.57 Elevation Data: Marker: 37.57' Utility Top: 34.97' Utility Bottom: N/A Test Hole Notes: Hub and tack set over center of the utility. _____ _____ _____ |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **1A**
Project Name: **PERRY POINT**
Project Number: **TEST HOLES**
Project Client: **MD23-045**
AMT

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/05/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering


CNC Civil Services

Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 2 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Excavation Crew: KB AB DF | |
| Utility Requested: Gas | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Gas | |
| Utility Material: Wrapped Steel | |
| Utility Color: Yellow | |
| Nominal Utility Size: 2" | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 2.5" | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input checked="" type="checkbox"/> N/A <input type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 2.41' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NE | |
| Marker Set | Test Hole Survey Information: Field Surveyed By: CNC Civil Services Survey Control Established By: AMT Engineering Survey Coordinates: Northing: 687741.06 Easting: 1575740.89 Elevation: 37.63 Elevation Data: Marker: 37.63' Utility Top: 35.22' Utility Bottom: N/A Test Hole Notes: Hub and tack set over center of utility. _____ _____ _____ |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: 2

PERRY POINT

Project Name: TEST HOLES

Project Number: MD23-045

Project Client: AMT

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/05/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering


CNC Civil Services

Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 2A | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Excavation Crew: KB AB DF | |
| Utility Requested: Unknown | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Water | |
| Utility Material: Copper | |
| Utility Color: Copper | |
| Nominal Utility Size: 1.5" | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 1.75" | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input checked="" type="checkbox"/> N/A <input type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 3.42' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| N | |
| Marker Set | Test Hole Survey Information: Field Surveyed By: CNC Civil Services Survey Control Established By: AMT Engineering Survey Coordinates: Northing: 687743.71 Easting: 1575741.98 Elevation: 37.60 Elevation Data: Marker: 37.60' Utility Top: 34.18' Utility Bottom: N/A Test Hole Notes: Hub and tack set over center of utility. _____ _____ _____ |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **2A**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/05/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering


CNC Civil Services

Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|---------------------------------|--|
| Test Hole Number: 2B | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Excavation Crew: KB AB DF | |
| Utility Requested: Unknown | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Unknown | |
| Utility Material: Unknown | |
| Utility Color: Black | |
| Nominal Utility Size: 2.5" | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 3" | |
| Overall Width: N/A | |
| Utility Owner: N/A | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input checked="" type="checkbox"/> N/A <input type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 3.24' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| N | |
| Marker Set | |
| PK <input type="checkbox"/> | Test Hole Survey Information: Field Surveyed By: CNC Civil Services Survey Control Established By: AMT Engineering Survey Coordinates: Northing: 687743.73 Easting: 1575742.47 Elevation: 37.58 Elevation Data: Marker: 37.58' Utility Top: 34.34' Utility Bottom: N/A Test Hole Notes: Hub and tack set over center of utility. _____ _____ _____ |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **2B**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/05/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 3 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Electric | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Electric | |
| Utility Material: Concrete Duct | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | |
| O.D. Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | |
| Pavement Thickness: N/A (Grass) | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |

| | |
|--|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 2.87' | |
| Cover (Bottom) | |
| 3.78' | |
| Drawn Facing | |
| SW | |
| Marker Set | Test Hole Survey Information: Field Surveyed By: CNC Civil Services Survey Control Established By: AMT Engineering Survey Coordinates: Northing: 687794.71 Easting: 1575785.23 Elevation: 38.40 Elevation Data: Marker: 38.40' Utility Top: 35.53' Utility Bottom: 31.75' Test Hole Notes: Hub and tack set over north edge of electric duct. |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

Test Hole Vicinity Sketch:



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **3**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/05/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 4 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Communication | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Communication | |
| Utility Material: Concrete Duct | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|----------------|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 1.60' | |
| Cover (Bottom) | |
| 3.08' | |
| Drawn Facing | |
| NW | |
| Marker Set | PK <input type="checkbox"/> Hub & Tack <input checked="" type="checkbox"/> Chis. "X" <input type="checkbox"/> |
| | |
| | |

| | | |
|--|---|------------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: | Easting: | Elevation: |
| 687819.70 | 1575818.03 | 38.36 |
| Elevation Data: | | |
| Marker: 38.36' | Utility Top: 36.76' | Utility Bottom: 35.28' |
| Test Hole Notes: | | |
| Hub and tack set over northern edge of Communication duct. | | |
| | | |
| | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **4**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/05/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 4A | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Unknown | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Unknown | |
| Utility Material: Concrete Duct | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|----------------|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 3.56' | |
| Cover (Bottom) | |
| 6.77' | |
| Drawn Facing | |
| SW | |
| Marker Set | PK <input type="checkbox"/> Hub & Tack <input checked="" type="checkbox"/> Chis. "X" <input type="checkbox"/> |
| | |
| | |

| Test Hole Survey Information: | | |
|---|---|------------------------|
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: | Easting: | Elevation: |
| 687820.54 | 1575818.23 | 38.43 |
| Elevation Data: | | |
| Marker: 38.43' | Utility Top: 34.87' | Utility Bottom: 31.66' |
| Test Hole Notes: | | |
| <u>Hub and tack set over north edge of unknown duct. Believed to existing steam duct.</u> | | |
| | | |
| | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **4A**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/06/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 5 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Electric | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Electric | |
| Utility Material: Concrete Duct | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | |
| O.D. Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | |
| Pavement Thickness: N/A (Grass) | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |

| | |
|--|--|
| Cover (Top) | Test Hole Profile Sketch: |
| 1.00' | |
| Cover (Bottom) | |
| 1.73' | |
| Drawn Facing | |
| N | |
| Marker Set | Test Hole Notes: Hub and tack set over east edge of electric duct. |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

| | | |
|--|---|------------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: 687835.08 | Easting: 1575844.85 | Elevation: 38.91 |
| Elevation Data: | | |
| Marker: 38.91' | Utility Top: 37.91' | Utility Bottom: 37.18' |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **5**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/06/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 5A | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Water | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Water | |
| Utility Material: Unknown See Note | |
| Utility Color: N/A | |
| Nominal Utility Size: Unknown See Note | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 5" | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|--|
| Cover (Top) | Test Hole Profile Sketch: |
| 4.08' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NW | |
| Marker Set | |
| PK <input type="checkbox"/> | Test Hole Notes: <u>Hub and tack set over approximate crown of utility. Utility is corroded at time of excavation unable to determine pipe material.</u> |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

| | | |
|--|---|---------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: 687829.06 | Easting: 1575859.20 | Elevation: 39.03 |
| Elevation Data: | | |
| Marker: 39.03' | Utility Top: 34.95' | Utility Bottom: N/A |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **5A**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/06/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 5B | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Communication | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Communication | |
| Utility Material: Concrete Duct | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |

| | |
|--|--------------------------------------|
| Cover (Top) | Test Hole Profile Sketch: |
| 2.97' | |
| Cover (Bottom) | |
| 3.86' | |
| Drawn Facing | |
| NW | |
| Marker Set | |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

| | | |
|--|---|------------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: 687830.17 | Easting: 1575860.94 | Elevation: 39.11 |
| Elevation Data: | | |
| Marker: 39.11' | Utility Top: 36.14' | Utility Bottom: 35.25' |
| Test Hole Notes: | | |
| Hub and tack set over west edge of communication duct. | | |
| | | |
| | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **5B**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION

NO PICTURE

Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/06/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 5C | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Excavation Crew: KB AB DF | |
| Utility Requested: Communication | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Communication | |
| Utility Material: Concrete Duct | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|--------------------------------------|
| Cover (Top) | Test Hole Profile Sketch: |
| 1.82' | |
| Cover (Bottom) | |
| 3.19' | |
| Drawn Facing | |
| NE | |
| Marker Set | |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

| | | |
|---|---|------------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: 687834.65 | Easting: 1575845.73 | Elevation: 38.92 |
| Elevation Data: | | |
| Marker: 38.92' | Utility Top: 37.10' | Utility Bottom: 35.73' |
| Test Hole Notes: | | |
| Hub and tack set over eastern edge of communication duct. | | |
| | | |
| | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **5C**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/06/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 5D | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Water | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Unknown | |
| Utility Material: Direct Buried Cable | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 1" | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|---|--------------------------------------|
| Cover (Top) | Test Hole Profile Sketch: |
| 2.84' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NE | |
| Marker Set | |
| PK <input type="checkbox"/> Hub & Tack <input checked="" type="checkbox"/> Chis. "X" <input type="checkbox"/> | |

| | | |
|--|---|---------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: 687829.67 | Easting: 1575858.08 | Elevation: 38.98 |
| Elevation Data: | | |
| Marker: 38.98' | Utility Top: 36.14' | Utility Bottom: N/A |
| Test Hole Notes: | | |
| Hub and tack set over center of utility. | | |
| | | |
| | | |
| | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **5D**
Project Name: **PERRY POINT**
Project Number: **TEST HOLES**
Project Client: **MD23-045**
AMT

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/12/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 6 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB DB JB | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Steam | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input type="checkbox"/> Gravel <input type="checkbox"/> Wet <input checked="" type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Steam | |
| Utility Material: Concrete | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: 31" | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|--------------------------------------|
| Cover (Top) | Test Hole Profile Sketch: |
| 4.40' | |
| Cover (Bottom) | |
| See Note | |
| Drawn Facing | |
| NW | |
| Marker Set | |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

| | | |
|--|---|---------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: | Easting: | Elevation: |
| 687216.61 | 1576105.41 | 37.44 |
| Elevation Data: | | |
| Marker: 37.44' | Utility Top: 33.04' | Utility Bottom: N/A |
| Test Hole Notes: | | |
| Hub and tack set over north edge of | | |
| footer. Steam line believed to be incased in | | |
| concrete. Bottom measurement to top of | | |
| footer 4.77'. Unable to obtain bottom. | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **6**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/12/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 6A | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB DB JB | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Steam | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input type="checkbox"/> Gravel <input type="checkbox"/> Wet <input checked="" type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Steam | |
| Utility Material: Concrete | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: 31" | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|--------------------------------------|
| Cover (Top) | Test Hole Profile Sketch: |
| 4.47' | |
| Cover (Bottom) | |
| See Note | |
| Drawn Facing | |
| NW | |
| Marker Set | |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

| | | |
|--|---|---------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: | Easting: | Elevation: |
| 687214.24 | 1576104.65 | 37.57 |
| Elevation Data: | | |
| Marker: 37.57' | Utility Top: 33.10' | Utility Bottom: N/A |
| Test Hole Notes: | | |
| Hub and tack set over south edge of | | |
| footer. Steam line believed to be incased in | | |
| concrete. Bottom measurement to top of | | |
| footer 4.77'. Unable to obtain bottom. | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **6A**
Project Name: **PERRY POINT**
Project Number: **TEST HOLES**
Project Client: **MD23-045**
AMT

ORIGINAL SITE CONDITION




SITE RESTORATION CONDITION




TEST HOLE EXCAVATION OBSERVATION



| | | | | | | | | | | | | |
|--|---|--|--|-----------|----------|------------|-----------|------------|-------|----------------|---------------------|---------------------|
| Point of Contact: Daniel Schriever, LS | | <div><h1>CNC Civil Services</h1><div>Project Name: PERRY POINT STEAM UPDATE PROJECT</div></div> | | | | | | | | | | |
| Phone Number: (443) 994-7285 | | | | | | | | | | | | |
| Date Performed: 12/06/2023 | | | | | | | | | | | | |
| Project Number: MD23-045 | | | | | | | | | | | | |
| Project Location: Perry Point, MD | | | | | | | | | | | | |
| Requested By: AMT Engineering | | | | | | | | | | | | |
| Utility Field Excavation Information | | | | | | | | | | | | |
| Test Hole Number: 7 | | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> | | | | | | | | | | |
| Excavation Crew: KB DB JB | | | | | | | | | | | | |
| Utility Requested: Electric | | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input type="checkbox"/> Gravel <input type="checkbox"/> Wet <input checked="" type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> | | | | | | | | | | |
| Utility Found: Electric Conduit | | | | | | | | | | | | |
| Utility Material: Plastic | | | | | | | | | | | | |
| Utility Color: Green | | | | | | | | | | | | |
| Nominal Utility Size: 1.5" | | | | | | | | | | | | |
| O.D. Utility Size: 1.5" | | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> | | | | | | | | | | |
| Overall Width: N/A | | | | | | | | | | | | |
| Utility Owner: Perry Point VA Hospital | | | | | | | | | | | | |
| Pavement Thickness: N/A (Grass) | | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> | | | | | | | | | | |
| Cover (Top) | <div>Test Hole Profile Sketch:</div>  | | | | | | | | | | | |
| 3.16' | | | | | | | | | | | | |
| Cover (Bottom) | | | | | | | | | | | | |
| N/A | | | | | | | | | | | | |
| Drawn Facing | | | | | | | | | | | | |
| NE | | | | | | | | | | | | |
| Marker Set | <div>Test Hole Survey Information:</div> <div>Field Surveyed By: CNC Civil Services Survey Control Established By: AMT Engineering</div> <div>Survey Coordinates:</div> <table><tr><td>Northing:</td><td>Easting:</td><td>Elevation:</td></tr><tr><td>687194.01</td><td>1576221.35</td><td>35.79</td></tr></table> <div>Elevation Data:</div> <table><tr><td>Marker: 35.79'</td><td>Utility Top: 32.63'</td><td>Utility Bottom: N/A</td></tr></table> <div>Test Hole Notes:</div> <div>Hub and tack set over center of electric conduit.</div> | | | Northing: | Easting: | Elevation: | 687194.01 | 1576221.35 | 35.79 | Marker: 35.79' | Utility Top: 32.63' | Utility Bottom: N/A |
| Northing: | Easting: | Elevation: | | | | | | | | | | |
| 687194.01 | 1576221.35 | 35.79 | | | | | | | | | | |
| Marker: 35.79' | Utility Top: 32.63' | Utility Bottom: N/A | | | | | | | | | | |
| PK <input type="checkbox"/> | | | | | | | | | | | | |
| Hub & Tack <input checked="" type="checkbox"/> | | | | | | | | | | | | |
| Chis. "X" <input type="checkbox"/> | | | | | | | | | | | | |

Test Hole Vicinity Sketch:



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: 7

PERRY POINT

Project Name: TEST HOLES

Project Number: MD23-045

Project Client: AMT

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/06/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering


CNC Civil Services

Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 8 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Excavation Crew: KB DB JB | |
| Utility Requested: Unknown | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input type="checkbox"/> Gravel <input type="checkbox"/> Wet <input checked="" type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Unknown | |
| Utility Material: Plastic | |
| Utility Color: Green | |
| Nominal Utility Size: 12" | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 13" | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 5.57' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NE | |
| Marker Set | |
| PK <input type="checkbox"/> | Test Hole Survey Information: Field Surveyed By: CNC Civil Services Survey Control Established By: AMT Engineering Survey Coordinates: Northing: 687196.28 Easting: 1576248.01 Elevation: 35.42 Elevation Data: Marker: 35.42' Utility Top: 29.85' Utility Bottom: N/A Test Hole Notes: Hub and tack set over crown of unknown pipe. _____ _____ _____ |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: 8

PERRY POINT

Project Name: TEST HOLES

Project Number: MD23-045

Project Client: AMT

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/06/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 9 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB DB JB | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Electric | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Electric Conduit | |
| Utility Material: Plastic | |
| Utility Color: Grey | |
| Nominal Utility Size: 2" | |
| O.D. Utility Size: 2" | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | |
| Pavement Thickness: N/A (Grass) | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |

| | |
|---|--------------------------------------|
| Cover (Top) | Test Hole Profile Sketch: |
| 2.83' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NW | |
| Marker Set | |
| PK <input type="checkbox"/> Hub & Tack <input checked="" type="checkbox"/> Chis. "X" <input type="checkbox"/> | |

| | | |
|---|---|---------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: 687190.27 | Easting: 1576270.45 | Elevation: 35.52 |
| Elevation Data: | | |
| Marker: 35.52' | Utility Top: 32.69' | Utility Bottom: N/A |
| Test Hole Notes: | | |
| Hub and tack set over center of electric conduit. | | |
| | | |
| | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **9**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION

NO PICTURE

Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/06/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering


CNC Civil Services

Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 10 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Excavation Crew: KB DB JB | |
| Utility Requested: Electric | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Electric | |
| Utility Material: Direct Buried | |
| Utility Color: Black | |
| Nominal Utility Size: (5) 1" | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: 6" | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 2.35' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NW | |
| Marker Set | |
| PK <input type="checkbox"/> | Test Hole Survey Information: Field Surveyed By: CNC Civil Services Survey Control Established By: AMT Engineering Survey Coordinates: Northing: 687190.60 Easting: 1576278.63 Elevation: 35.63 Elevation Data: Marker: 35.63' Utility Top: 33.28' Utility Bottom: N/A Test Hole Notes: Hub and tack set over center of electric configuration. |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **10**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/06/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 11 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB DB JB | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Steam | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Steam | |
| Utility Material: Concrete | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: N/A" | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|---|--------------------------------------|
| Cover (Top) | Test Hole Profile Sketch: |
| 3.54' | |
| Cover (Bottom) | |
| See Note | |
| Drawn Facing | |
| NW | |
| Marker Set | |
| PK <input type="checkbox"/> Hub & Tack <input checked="" type="checkbox"/> Chis. "X" <input type="checkbox"/> | |

| | | |
|---|---|---------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: | Easting: | Elevation: |
| 687188.03 | 1576283.66 | 35.73 |
| Elevation Data: | | |
| Marker: 35.73' | Utility Top: 32.19' | Utility Bottom: N/A |
| Test Hole Notes: | | |
| Hub and tack set over north edge of steam duct. Unable to obtain bottom due to soil conditions. Also unknown utility found. see form 11A for details. | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **11**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION




Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/06/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 11A | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DB | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Steam | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Unknown See Notes | |
| Utility Material: Terra Cotta | |
| Utility Color: Terra Cotta | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 5" | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|--|
| Cover (Top) | Test Hole Profile Sketch:  |
| 4.66' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NE | |
| Marker Set | |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

| | | |
|---|---|---------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: | Easting: | Elevation: |
| 687188.28 | 1576285.49 | 35.82 |
| Elevation Data: | | |
| Marker: 35.82' | Utility Top: 31.16' | Utility Bottom: N/A |
| Test Hole Notes: | | |
| Hub and tack set over crown of utility, believed to be possible roof drain. | | |
| | | |
| | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **11A**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



CNC Civil Services


Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | | | | |
|-----------------------|-------------------------|---------------------|---|---|
| Test Hole Number: | 12 | Utility Condition: | Poor <input type="checkbox"/> | Fair <input checked="" type="checkbox"/> |
| Excavation Crew: | KB AB DB | | Good <input type="checkbox"/> | See Notes <input type="checkbox"/> |
| Utility Requested: | Steam | Soil Condition: | Clay <input type="checkbox"/> | Sand <input checked="" type="checkbox"/> |
| Utility Found: | Steam | | Rocks <input checked="" type="checkbox"/> | Moist <input checked="" type="checkbox"/> |
| Utility Material: | Concrete | | Gravel <input type="checkbox"/> | Wet <input type="checkbox"/> |
| Utility Color: | Grey | | Dry <input type="checkbox"/> | Hard <input type="checkbox"/> |
| | | | Soft <input checked="" type="checkbox"/> | See Notes <input type="checkbox"/> |
| Nominal Utility Size: | N/A | Ground Type: | Grass <input checked="" type="checkbox"/> | Gravel <input type="checkbox"/> |
| O.D. Utility Size: | N/A | | Asphalt <input type="checkbox"/> | Concrete <input type="checkbox"/> |
| Overall Width: | N/A | | Brick <input type="checkbox"/> | Pavers <input type="checkbox"/> |
| Utility Owner: | Perry Point VA Hospital | Pavement Condition: | Poor <input type="checkbox"/> | Fair <input type="checkbox"/> |
| Pavement Thickness: | N/A (Grass) | | Good <input type="checkbox"/> | N/A <input checked="" type="checkbox"/> |

| | | | | |
|--|---|---|--------------------------------|--------------------------|
| Cover (Top) | <p align="center"><u>Test Hole Profile Sketch:</u></p> | <u>Test Hole Survey Information:</u> | | |
| 1.71' | | Field Surveyed By: | Survey Control Established By: | |
| Cover (Bottom) | | CNC Civil Services | AMT Engineering | |
| 4.23' | | <u>Survey Coordinates:</u> | | |
| Drawn Facing | | <u>Northing:</u> | <u>Easting:</u> | <u>Elevation:</u> |
| N | | 687221.14 | 1576387.36 | 34.16 |
| Marker Set | | <u>Elevation Data:</u> | | |
| PK <input type="checkbox"/> | Marker: 34.16' | Utility Top: 32.45' | Utility Bottom: 29.93' | |
| Hub & Tack <input checked="" type="checkbox"/> | <u>Test Hole Notes:</u> | | | |
| Chis. "X" <input type="checkbox"/> | <u>Hub and tack set over east edge of concrete.</u> | | | |
| | <u>Steam believed to be inside.</u> | | | |
| | | | | |
| | | | | |

Test Hole Vicinity Sketch:



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **12**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/13/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 20 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Excavation Crew: KB DB JB | |
| Utility Requested: Unknown | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Unknown Duct | |
| Utility Material: Concrete | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: N/A" | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|----------------|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 6.55' | |
| Cover (Bottom) | |
| 7.39' | |
| Drawn Facing | |
| NW | |
| Marker Set | PK <input type="checkbox"/> Hub & Tack <input checked="" type="checkbox"/> Chis. "X" <input type="checkbox"/> |
| | |
| | |

| Test Hole Survey Information: | | |
|--|---|------------------------|
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: | Easting: | Elevation: |
| 687541.45 | 1576538.51 | 36.15 |
| Elevation Data: | | |
| Marker: 36.15' | Utility Top: 29.61' | Utility Bottom: 28.76' |
| Test Hole Notes: | | |
| Hub and tack set over east edge of unknown duct. Believed to be communication. | | |
| | | |
| | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **20**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/12/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 21 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB DB JB | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Steam | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Steam | |
| Utility Material: Concrete | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: N/A" | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|--------------------------------------|
| Cover (Top) | Test Hole Profile Sketch: |
| 2.82' | |
| Cover (Bottom) | |
| 5.11' | |
| Drawn Facing | |
| SW | |
| Marker Set | |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

| | | |
|--|---|------------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: | Easting: | Elevation: |
| 687546.84 | 1576543.00 | 36.23 |
| Elevation Data: | | |
| Marker: 36.23' | Utility Top: 33.41' | Utility Bottom: 31.12' |
| Test Hole Notes: | | |
| Hub and tack set over south edge of steam duct footer. | | |
| | | |
| | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **21**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**


ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/11/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|---|
| Test Hole Number: 26 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Excavation Crew: KB AB DF | |
| Utility Requested: Electric | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Electric | |
| Utility Material: Concrete Duct | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|----------------|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 2.16' | |
| Cover (Bottom) | |
| 3.07' | |
| Drawn Facing | |
| SW | |
| Marker Set | PK <input type="checkbox"/> Hub & Tack <input checked="" type="checkbox"/> Chis. "X" <input type="checkbox"/> |
| | |
| | |

| | | |
|---|---|------------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: | Easting: | Elevation: |
| 687193.59 | 1577765.45 | 30.13 |
| Elevation Data: | | |
| Marker: 30.13' | Utility Top: 27.97' | Utility Bottom: 27.06' |
| Test Hole Notes: | | |
| Hub and tack set over northern edge of | | |
| electric duct. Test hole also found unknown | | |
| concrete under electric. See form 26A for | | |
| details | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **26**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/11/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|---|
| Test Hole Number: 26A | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Excavation Crew: KB AB DF | |
| Utility Requested: Electric | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Unknown Duct | |
| Utility Material: Concrete | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|----------------|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 3.37' | |
| Cover (Bottom) | |
| 5.73' | |
| Drawn Facing | |
| SW | |
| Marker Set | PK <input type="checkbox"/> Hub & Tack <input checked="" type="checkbox"/> Chis. "X" <input type="checkbox"/> |
| | |
| | |

| | | |
|--|---|------------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: | Easting: | Elevation: |
| 687196.44 | 1577762.85 | 30.10 |
| Elevation Data: | | |
| Marker: 30.10' | Utility Top: 26.73' | Utility Bottom: 24.37' |
| Test Hole Notes: | | |
| Hub and tack set over northern edge of unknown duct. | | |
| | | |
| | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **26A**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/11/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services

Project Name: PERRY POINT STEAM
 UPDATE PROJECT


Utility Field Excavation Information

| | |
|--|---|
| Test Hole Number: 27 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Water | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Water | |
| Utility Material: Unknown See note | |
| Utility Color: Black | |
| Nominal Utility Size: 1" | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 1.5" | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|--|
| Cover (Top) | Test Hole Profile Sketch: |
| 1.39' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NE | |
| Marker Set | Test Hole Notes: Hub and tack set over center of utility. Also found unknown concrete at 3.34'. Unable to obtain edge. |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

| | | |
|--|---|------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: | Easting: | Elevation: |
| 687184.81 | 157777.56 | 30.58 |

| | | |
|------------------------|---------------------|---------------------|
| Elevation Data: | | |
| Marker: 30.58' | Utility Top: 29.19' | Utility Bottom: N/A |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **27**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/11/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|---|
| Test Hole Number: 30 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Electric | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Electric | |
| Utility Material: Concrete Duct | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | |
| O.D. Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | |
| Pavement Thickness: N/A (Grass) | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |

| | |
|--|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 3.63' | |
| Cover (Bottom) | |
| 4.74' | |
| Drawn Facing | |
| NW | |
| Marker Set | Test Hole Notes: Hub and tack set over northern edge of electric duct. _____ _____ _____ |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

| | | |
|--|---|------------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: 687219.89 | Easting: 1577946.71 | Elevation: 33.64 |
| Elevation Data: | | |
| Marker: 33.64' | Utility Top: 30.01' | Utility Bottom: 28.90' |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **30**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/11/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering


CNC Civil Services

Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|---|
| Test Hole Number: 30A | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Electric | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Electric | |
| Utility Material: Concrete Duct | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 4.35' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NW | |
| Marker Set | Test Hole Survey Information: Field Surveyed By: CNC Civil Services Survey Control Established By: AMT Engineering Survey Coordinates: Northing: 687213.19 Easting: 1577939.92 Elevation: 33.14 Elevation Data: Marker: 33.14' Utility Top: 28.79' Utility Bottom: N/A Test Hole Notes: Hub and tack set over electric duct. Unable to obtain edge + bottom due to ground water/cave ins. |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **30A**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/11/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 30B | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Communications | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input type="checkbox"/> Gravel <input type="checkbox"/> Wet <input checked="" type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Communications | |
| Utility Material: Plastic | |
| Utility Color: Unknown See Note | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A See Note | |
| Overall Width: N/A See Note | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |

| | |
|--|--------------------------------------|
| Cover (Top) | Test Hole Profile Sketch: |
| 4.52' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NW | |
| Marker Set | |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

| | | |
|--|---|---------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: 687220.32 | Easting: 1577946.99 | Elevation: 33.65 |
| Elevation Data: | | |
| Marker: 33.65' | Utility Top: 29.13' | Utility Bottom: N/A |
| Test Hole Notes: | | |
| Hub and tack set over utility. Unable to obtain accurate size and material due to cave ins and ground water. | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **30B**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/07/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering


CNC Civil Services

Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 31 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Water | Soil Condition: Clay <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input checked="" type="checkbox"/> Soft <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Unknown | |
| Utility Material: Concrete | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 4.06' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| N | |
| Marker Set | Test Hole Survey Information: Field Surveyed By: CNC Civil Services Survey Control Established By: AMT Engineering Survey Coordinates: Northing: 687249.01 Easting: 1577999.60 Elevation: 34.06 Elevation Data: Marker: 34.06' Utility Top: 30.0' Utility Bottom: N/A Test Hole Notes: <u>Hub and tack set over concrete structure.</u> <u>Crews encountered unsafe digging conditions</u> <u>in which steam was coming out of hole.</u> <u>moved test hole east . see form 31A.</u> |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **31**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION

NO PICTURE

Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/07/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 31A | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Water | Soil Condition: Clay <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input checked="" type="checkbox"/> Soft <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Water | |
| Utility Material: Cast Iron | |
| Utility Color: Black | |
| Nominal Utility Size: 10" | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 10.5" | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|--------------------------------------|
| Cover (Top) | Test Hole Profile Sketch: |
| 3.60' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NW | |
| Marker Set | |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

| | | |
|--|---|---------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: | Easting: | Elevation: |
| 687243.30 | 1578008.26 | 34.05 |
| Elevation Data: | | |
| Marker: 34.05' | Utility Top: 30.45' | Utility Bottom: N/A |
| Test Hole Notes: | | |
| Hub and tack set over crown of utility. | | |
| | | |
| | | |
| | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **31A**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/07/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 32 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Unknown | Soil Condition: Clay <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input checked="" type="checkbox"/> Soft <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Unknown | |
| Utility Material: Direct Buried | |
| Utility Color: Black | |
| Nominal Utility Size: 2" | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 2" | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|--------------------------------------|
| Cover (Top) | Test Hole Profile Sketch: |
| 2.27' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NW | |
| Marker Set | |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

| | | |
|--|---|---------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: 687259.48 | Easting: 1578021.99 | Elevation: 33.98 |
| Elevation Data: | | |
| Marker: 33.98' | Utility Top: 31.71' | Utility Bottom: N/A |
| Test Hole Notes: | | |
| Hub and tack set over center of utility. | | |
| | | |
| | | |
| | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **32**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



| |
|--|
| Point of Contact: Daniel Schriever, LS |
| Phone Number: (443) 994-7285 |
| Date Performed: 12/07/2023 |
| Project Number: MD23-045 |
| Project Location: Perry Point, MD |
| Requested By: AMT Engineering |

CNC Civil Services


Project Name: PERRY POINT STEAM UPDATE PROJECT

Utility Field Excavation Information

| | |
|---------------------------------|--|
| Test Hole Number: 33 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Excavation Crew: KB AB DF | |
| Utility Requested: Steam | Soil Condition: Clay <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input checked="" type="checkbox"/> Soft <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: See Note | |
| Utility Material: N/A | |
| Utility Color: N/A | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: N/A | |
| Utility Owner: N/A | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|---|--------------------------------------|
| Cover (Top) | Test Hole Profile Sketch: |
| SEE NOTES | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NE | |
| Marker Set | |
| PK <input type="checkbox"/> Hub & Tack <input checked="" type="checkbox"/> Chis. "X" <input type="checkbox"/> | |

| | | |
|--|---|---------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: 687279.82 | Easting: 1578054.68 | Elevation: 34.24 |
| Elevation Data: | | |
| Marker: 34.24' | Utility Top: N/A | Utility Bottom: N/A |
| Test Hole Notes: | | |
| Hub and tack set over center of test hole. | | |
| crews cleared to 6' no utilities were found. | | |
| See form TH-33A for additional information. | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **33**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/07/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering


CNC Civil Services

Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|---------------------------------|--|
| Test Hole Number: 33A | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Steam | Soil Condition: Clay <input checked="" type="checkbox"/> Sand <input type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input checked="" type="checkbox"/> Soft <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: See Note | |
| Utility Material: See Note | |
| Utility Color: N/A | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: N/A | |
| Utility Owner: N/A | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|--|
| Cover (Top) | Test Hole Profile Sketch: |
| SEE NOTES | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NE | |
| Marker Set | |
| PK <input type="checkbox"/> | Test Hole Survey Information: Field Surveyed By: CNC Civil Services Survey Control Established By: AMT Engineering Survey Coordinates: Northing: 687276.39 Easting: 1578055.24 Elevation: 34.21 Elevation Data: Marker: 34.21' Utility Top: 30.24' Utility Bottom: N/A Test Hole Notes: <u>Hub and tack set over south west edge of highest concrete duct. Crew found multiple extra utilities in test hole see profile sketch for depths.</u> |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **33A**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/20/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering


CNC Civil Services

Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 40 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Electric | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Electric | |
| Utility Material: Direct Buried | |
| Utility Color: Black | |
| Nominal Utility Size: 0.5" (2) | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 0.5" (2) | |
| Overall Width: 1.25" | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|--|
| Cover (Top) | Test Hole Profile Sketch: |
| 1.60' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NW | |
| Marker Set | |
| PK <input type="checkbox"/> | Test Hole Survey Information: Field Surveyed By: CNC Civil Services Survey Control Established By: AMT Engineering Survey Coordinates: Northing: 686900.90 Easting: 1577083.70 Elevation: 25.93 Elevation Data: Marker: 25.93' Utility Top: 24.33' Utility Bottom: N/A Test Hole Notes: Hub and tack set over center of the utility configuration. |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **40**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/20/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 41 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Electric | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Electric | |
| Utility Material: Concrete Duct | |
| Utility Color: N/A | |
| Nominal Utility Size: N/A | |
| O.D. Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | |
| Pavement Thickness: N/A (Grass) | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |

| | |
|--|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 2.30' | |
| Cover (Bottom) | |
| 3.67' | |
| Drawn Facing | |
| SE | |
| Marker Set | |
| PK <input type="checkbox"/> | Test Hole Notes: <u>Hub and tack set over eastern edge of duct.</u> |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

| | | |
|--|---|------------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: | Easting: | Elevation: |
| 686884.51 | 1577084.67 | 25.06 |
| Elevation Data: | | |
| Marker: 25.06' | Utility Top: 22.76' | Utility Bottom: 21.39' |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **41**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



| |
|--|
| Point of Contact: Daniel Schriever, LS |
| Phone Number: (443) 994-7285 |
| Date Performed: 12/20/2023 |
| Project Number: MD23-045 |
| Project Location: Perry Point, MD |
| Requested By: AMT Engineering |

CNC Civil Services


Project Name: PERRY POINT STEAM UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 41A | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Excavation Crew: KB AB DF | |
| Utility Requested: Electric | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Electric | |
| Utility Material: Direct Buried | |
| Utility Color: Black | |
| Nominal Utility Size: 0.5" | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 0.5" | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|-----------------------------|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 2.41' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NW | |
| Marker Set | |
| PK <input type="checkbox"/> | <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> |
| Hub & Tack | |
| Chis. "X" | |

| | | |
|--|--|---------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: 686882.52 | Easting: 1577083.59 | Elevation: 24.88 |
| Elevation Data: | | |
| Marker: 24.88' | Utility Top: 22.47' | Utility Bottom: N/A |
| Test Hole Notes: | | |
| Hub and tack set over center of the utility. | | |
| | | |
| | | |
| | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **41A**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/20/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering


CNC Civil Services

Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 42 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Electric | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Electric | |
| Utility Material: Concrete Duct | |
| Utility Color: N/A | |
| Nominal Utility Size: N/A | |
| O.D. Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | |
| Pavement Thickness: N/A (Grass) | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |

| | |
|--|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 1.80' | |
| Cover (Bottom) | |
| 3.42' | |
| Drawn Facing | |
| SE | |
| Marker Set | Test Hole Survey Information: Field Surveyed By: CNC Civil Services Survey Control Established By: AMT Engineering Survey Coordinates: Northing: 686877.29 Easting: 1577082.21 Elevation: 24.64 Elevation Data: Marker: 24.64' Utility Top: 22.84' Utility Bottom: 21.22' Test Hole Notes: <u>Hub and tack set over western edge of duct.</u> <u>Crew also discovered .5" direct buried cable with duct.</u> |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **42**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION




TEST HOLE EXCAVATION OBSERVATION



| | |
|--|---|
| Point of Contact: Daniel Schriever, LS | <h1 style="margin: 0;">CNC Civil Services</h1> |
| Phone Number: (443) 994-7285 | |
| Date Performed: 12/20/2023 | |
| Project Number: MD23-045 | |
| Project Location: Perry Point, MD | |
| Requested By: AMT Engineering | Project Name: PERRY POINT STEAM UPDATE PROJECT |

| Utility Field Excavation Information | | |
|--|---|--|
| Test Hole Number: 42A | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> | |
| Excavation Crew: KB AB DF | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> | |
| Utility Requested: Electric | | |
| Utility Found: Electric | | |
| Utility Material: Concrete Duct | | |
| Utility Color: N/A | | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> | |
| O.D. Utility Size: N/A | | |
| Overall Width: N/A | | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> | |
| Pavement Thickness: N/A (Grass) | | |
| Cover (Top) | Test Hole Survey Information: Field Surveyed By: CNC Civil Services Survey Control Established By: AMT Engineering <div style="display: flex; justify-content: space-between;"> <div> <u>Survey Coordinates:</u> Northing: 686875.31 Easting: 1577081.37 Elevation: 24.55 </div> <div> <u>Elevation Data:</u> Marker: 24.64' Utility Top: 20.76' Utility Bottom: 19.86' </div> </div> | |
| 3.79' | | |
| Cover (Bottom) | | |
| 4.69' | | |
| Drawn Facing | | |
| SE | | |
| Marker Set | Test Hole Notes: <u>Hub and tack set over western edge of duct.</u> | |
| PK <input type="checkbox"/> | | |
| Hub & Tack <input checked="" type="checkbox"/> | | |
| Chis. "X" <input type="checkbox"/> | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **42A**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



| |
|--|
| Point of Contact: Daniel Schriever, LS |
| Phone Number: (443) 994-7285 |
| Date Performed: 12/20/2023 |
| Project Number: MD23-045 |
| Project Location: Perry Point, MD |
| Requested By: AMT Engineering |

CNC Civil Services


Project Name: PERRY POINT STEAM UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 43 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Excavation Crew: KB AB DF | |
| Utility Requested: Water | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Water | |
| Utility Material: Unknown | |
| Utility Color: Black | |
| Nominal Utility Size: 14" | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 15" | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 4.17' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NW | |
| Marker Set | |
| PK <input type="checkbox"/> | Test Hole Notes: Hub and tack set over crown of the utility. |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

| | | |
|---------------------------------------|--|---------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: 686846.83 | Easting: 1577090.78 | Elevation: 23.28 |
| Elevation Data: | | |
| Marker: 23.28' | Utility Top: 19.11' | Utility Bottom: N/A |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **43**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



| |
|--|
| Point of Contact: Daniel Schriever, LS |
| Phone Number: (443) 994-7285 |
| Date Performed: 12/20/2023 |
| Project Number: MD23-045 |
| Project Location: Perry Point, MD |
| Requested By: AMT Engineering |




Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 43A | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Excavation Crew: KB AB DF | |
| Utility Requested: Water | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Water | |
| Utility Material: Unknown | |
| Utility Color: Black | |
| Nominal Utility Size: 14" | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 15" | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|-----------------------------|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 3.90' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NW | |
| Marker Set | |
| PK <input type="checkbox"/> | <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> |
| Hub & Tack | |
| Chis. "X" | |

| | | |
|---|--|---------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: 686843.47 | Easting: 1577089.79 | Elevation: 23.10 |
| Elevation Data: | | |
| Marker: 23.10' | Utility Top: 19.20' | Utility Bottom: N/A |
| Test Hole Notes: | | |
| Hub and tack set over crown of the utility. | | |
| | | |
| | | |
| | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **43A**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/20/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 46 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Excavation Crew: KB AB DF | |
| Utility Requested: Electric | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Electric | |
| Utility Material: Direct Buried | |
| Utility Color: Black | |
| Nominal Utility Size: 0.5" (2) | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 0.5" (2) | |
| Overall Width: 1.25" | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 1.68' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NW | |
| Marker Set | |
| PK <input type="checkbox"/> | Test Hole Notes: Hub and tack set over center of the utility configuration. |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

| | | |
|--|---|---------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: 686688.84 | Easting: 1577314.56 | Elevation: 22.78 |
| Elevation Data: | | |
| Marker: 22.78' | Utility Top: 21.10' | Utility Bottom: N/A |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **46**
Project Name: **PERRY POINT**
Project Number: **TEST HOLES**
Project Client: **MD23-045**
AMT

ORIGINAL SITE CONDITION





SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



| | | | |
|--|---|--|--|
| Point of Contact: Daniel Schriever, LS | | <div><h1>CNC Civil Services</h1><div>Project Name: PERRY POINT STEAM UPDATE PROJECT</div></div> | |
| Phone Number: (443) 994-7285 | | | |
| Date Performed: 12/21/2023 | | | |
| Project Number: MD23-045 | | | |
| Project Location: Perry Point, MD | | | |
| Requested By: AMT Engineering | | | |
| Utility Field Excavation Information | | | |
| Test Hole Number: 47 | | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> | |
| Excavation Crew: KB AB DF | | | |
| Utility Requested: Water | | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> | |
| Utility Found: Water | | | |
| Utility Material: Cast Iron | | | |
| Utility Color: Black | | | |
| Nominal Utility Size: 6" | | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> | |
| O.D. Utility Size: 6.5" | | | |
| Overall Width: N/A | | | |
| Utility Owner: Perry Point VA Hospital | | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> | |
| Pavement Thickness: N/A (Grass) | | | |
| Cover (Top) | <div>Test Hole Profile Sketch:</div>  | Test Hole Survey Information: | |
| 3.37' | | Field Surveyed By: CNC Civil Services Survey Control Established By: AMT Engineering | |
| Cover (Bottom) | | Survey Coordinates: | |
| N/A | | Northing: 686677.14 Easting: 1577370.81 Elevation: 23.43 | |
| Drawn Facing | | Elevation Data: | |
| NE | | Marker: 23.43' Utility Top: 20.06' Utility Bottom: N/A | |
| Marker Set | Test Hole Notes: | | |
| PK <input type="checkbox"/> | Hub and tack set over crown of the utility. | | |
| Hub & Tack <input checked="" type="checkbox"/> | | | |
| Chis. "X" <input type="checkbox"/> | | | |
| Test Hole Vicinity Sketch: | | | |
|  | | | |

CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **47**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/21/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering


CNC Civil Services

Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 47A | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Electric | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Electric | |
| Utility Material: Direct Buried | |
| Utility Color: Black | |
| Nominal Utility Size: 0.5" (2) | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 0.5" (2) | |
| Overall Width: 2" | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | | | | |
|--|--|--|---------------------|------------------|
| Cover (Top) | Test Hole Profile Sketch: | Test Hole Survey Information: | | |
| 1.95' | | Field Surveyed By: CNC Civil Services | | |
| Cover (Bottom) | | Survey Control Established By: AMT Engineering | | |
| N/A | | Survey Coordinates: | | |
| Drawn Facing | | Northing: 686677.43 | Easting: 1577370.18 | Elevation: 23.40 |
| N | | Elevation Data: | | |
| Marker Set | Marker: 23.40' | Utility Top: 21.45' | Utility Bottom: N/A | |
| PK <input type="checkbox"/> | Test Hole Notes: | | | |
| Hub & Tack <input checked="" type="checkbox"/> | Hub and tack set over center of the utility configuration. | | | |
| Chis. "X" <input type="checkbox"/> | | | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **47A**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/21/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 48 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Electric | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Electric | |
| Utility Material: Plastic | |
| Utility Color: White | |
| Nominal Utility Size: 1.25" | |
| O.D. Utility Size: 1.25" | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | |
| Pavement Thickness: N/A (Grass) | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |

| | |
|---|--------------------------------------|
| Cover (Top) | Test Hole Profile Sketch: |
| 1.16' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NW | |
| Marker Set | |
| PK <input type="checkbox"/> Hub & Tack <input checked="" type="checkbox"/> Chis. "X" <input type="checkbox"/> | |

| | | |
|--|---|---------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: 686633.57 | Easting: 1577417.41 | Elevation: 23.67 |
| Elevation Data: | | |
| Marker: 23.67' | Utility Top: 22.51' | Utility Bottom: N/A |
| Test Hole Notes: | | |
| Hub and tack set over center of the utility. | | |
| | | |
| | | |
| | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **48**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/21/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering


CNC Civil Services

Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 49 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Water | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Water | |
| Utility Material: Unknown | |
| Utility Color: White | |
| Nominal Utility Size: 14" | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 15" | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 5.56' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NW | |
| Marker Set | |
| PK <input type="checkbox"/> | Test Hole Survey Information: Field Surveyed By: CNC Civil Services Survey Control Established By: AMT Engineering Survey Coordinates: Northing: 686611.41 Easting: 1577475.01 Elevation: 24.11 Elevation Data: Marker: 24.11' Utility Top: 18.55' Utility Bottom: N/A Test Hole Notes: Hub and tack set over approximate crown of water pipe. _____ _____ _____ |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **49**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/21/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering


CNC Civil Services

Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 49A | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Water | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Water | |
| Utility Material: Unknown | |
| Utility Color: White | |
| Nominal Utility Size: 14" | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 15" | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|---|
| Cover (Top) | Test Hole Profile Sketch: |
| 5.59' | |
| Cover (Bottom) | |
| N/A | |
| Drawn Facing | |
| NW | |
| Marker Set | Test Hole Survey Information: Field Surveyed By: CNC Civil Services Survey Control Established By: AMT Engineering Survey Coordinates: Northing: 686608.97 Easting: 1577473.60 Elevation: 24.06 Elevation Data: Marker: 24.06' Utility Top: 18.47' Utility Bottom: N/A Test Hole Notes: Hub and tack set over approximate crown of water pipe. _____ _____ _____ |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **49A**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



| | | | |
|--|--------------------------------------|--|--|
| Point of Contact: Daniel Schriever, LS | | <div>CNC Civil Services</div> <div>Project Name: PERRY POINT STEAM UPDATE PROJECT</div> | |
| Phone Number: (443) 994-7285 | | | |
| Date Performed: 12/21/2023 | | | |
| Project Number: MD23-045 | | | |
| Project Location: Perry Point, MD | | | |
| Requested By: AMT Engineering | | | |
| Utility Field Excavation Information | | | |
| Test Hole Number: 50 | | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> | |
| Excavation Crew: KB AB DF | | Good <input type="checkbox"/> See Notes <input type="checkbox"/> | |
| Utility Requested: Electric | | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> | |
| Utility Found: Electric | | | |
| Utility Material: Concrete | | | |
| Utility Color: Grey | | | |
| Nominal Utility Size: N/A | | | |
| O.D. Utility Size: N/A | | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> | |
| Overall Width: N/A | | | |
| Utility Owner: Perry Point VA Hospital | | | |
| Pavement Thickness: N/A (Grass) | | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> | |
| Cover (Top) | <div>Test Hole Profile Sketch:</div> | | |
| 2.49' | | | |
| Cover (Bottom) | | | |
| 3.53' | | | |
| Drawn Facing | | | |
| NE | | | |
| Marker Set | | | |
| PK <input type="checkbox"/> | | | |
| Hub & Tack <input checked="" type="checkbox"/> | | | |
| Chis. "X" <input type="checkbox"/> | | | |
| Test Hole Survey Information: | | | |
| Field Surveyed By: CNC Civil Services | | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | | |
| Northing: | Easting: | Elevation: | |
| 686609.08 | 1577484.65 | 24.19 | |
| Elevation Data: | | | |
| Marker: 24.19' | Utility Top: 21.70' | Utility Bottom: N/A | |
| Test Hole Notes: | | | |
| Hub and tack set over eastern edge of electric duct. | | | |
| | | | |
| | | | |
| Test Hole Vicinity Sketch: | | | |
| | | | |

CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **50**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/21/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 51 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Unknown | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Unknown | |
| Utility Material: Concrete | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|--------------------------------------|
| Cover (Top) | Test Hole Profile Sketch: |
| 0.84' | |
| Cover (Bottom) | |
| 3.0' | |
| Drawn Facing | |
| NE | |
| Marker Set | |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

| | | |
|---|---|------------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: 686607.28 | Easting: 1577498.36 | Elevation: 24.11 |
| Elevation Data: | | |
| Marker: 24.11' | Utility Top: 23.27' | Utility Bottom: 21.11' |
| Test Hole Notes: | | |
| Hub and tack set over northern edge of electric duct. | | |
| | | |
| | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **51**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/21/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering


CNC Civil Services

Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 53 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Excavation Crew: KB AB DF | |
| Utility Requested: Water | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Water | |
| Utility Material: Cast Iron | |
| Utility Color: Black | |
| Nominal Utility Size: 8" | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 8.5" | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | | | | |
|--|--|--|---------------------|------------|
| Cover (Top) | Test Hole Profile Sketch: | Test Hole Survey Information: | | |
| 3.12' | | Field Surveyed By: CNC Civil Services | | |
| Cover (Bottom) | | Survey Control Established By: AMT Engineering | | |
| N/A | | Survey Coordinates: | | |
| Drawn Facing | | Northing: | Easting: | Elevation: |
| NE | | 686587.06 | 1577609.04 | 26.23 |
| Marker Set | Elevation Data: | | | |
| PK <input type="checkbox"/> | Marker: 26.23' | Utility Top: 23.11' | Utility Bottom: N/A | |
| Hub & Tack <input checked="" type="checkbox"/> | Test Hole Notes: | | | |
| Chis. "X" <input type="checkbox"/> | Hub and tack set over crown of water pipe. | | | |
| | See form #53A for parallel pipe details. | | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **53**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/21/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering


CNC Civil Services

Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 53A | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Excavation Crew: KB AB DF | |
| Utility Requested: Water | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Water | |
| Utility Material: Cast Iron | |
| Utility Color: Black | |
| Nominal Utility Size: 2" | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: 2" | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | | | | |
|--|---|--|---------------------|------------|
| Cover (Top) | Test Hole Profile Sketch: | Test Hole Survey Information: | | |
| 3.53' | | Field Surveyed By: CNC Civil Services | | |
| Cover (Bottom) | | Survey Control Established By: AMT Engineering | | |
| N/A | | Survey Coordinates: | | |
| Drawn Facing | | Northing: | Easting: | Elevation: |
| NE | | 686586.77 | 1577609.38 | 26.23 |
| Marker Set | Elevation Data: | | | |
| PK <input type="checkbox"/> | Marker: 26.23' | Utility Top: 22.70' | Utility Bottom: N/A | |
| Hub & Tack <input checked="" type="checkbox"/> | Test Hole Notes: | | | |
| Chis. "X" <input type="checkbox"/> | Hub and tack set over center of pipe running with 8" water. | | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **53A**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/21/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 54 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Communication | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Communication | |
| Utility Material: Concrete | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |

| | | | | |
|--|--|---------------------------------------|--|------------------------|
| Cover (Top) | Test Hole Profile Sketch: | Test Hole Survey Information: | | |
| 1.83' | | Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Cover (Bottom) | | Survey Coordinates: | | |
| 2.95' | | Northing: 686588.06 | Easting: 1577628.25 | Elevation: 26.63 |
| Drawn Facing | | Elevation Data: | | |
| NW | | Marker: 26.63' | Utility Top: 24.80' | Utility Bottom: 23.68' |
| Marker Set | Test Hole Notes: | | | |
| PK <input type="checkbox"/> | Hub and tack set over southern edge of communication duct. | | | |
| Hub & Tack <input checked="" type="checkbox"/> | | | | |
| Chis. "X" <input type="checkbox"/> | | | | |

Test Hole Vicinity Sketch:



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **54**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION




Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/21/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 55 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Electric | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Electric | |
| Utility Material: Concrete | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | | | | |
|--|--|--|------------------------|------------------|
| Cover (Top) | Test Hole Profile Sketch:  | Test Hole Survey Information: | | |
| 2.70' | | Field Surveyed By: CNC Civil Services | | |
| Cover (Bottom) | | Survey Control Established By: AMT Engineering | | |
| 3.71' | | Survey Coordinates: | | |
| Drawn Facing | | Northing: 686582.31 | Easting: 1577642.05 | Elevation: 26.75 |
| NW | | Elevation Data: | | |
| Marker Set | Marker: 26.75' | Utility Top: 24.05' | Utility Bottom: 23.04' | |
| PK <input type="checkbox"/> | Test Hole Notes: | | | |
| Hub & Tack <input checked="" type="checkbox"/> | Hub and tack set over southern edge of electric duct. | | | |
| Chis. "X" <input type="checkbox"/> | | | | |

Test Hole Vicinity Sketch:



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **55**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/21/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
 UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 59 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> |
| Excavation Crew: KB AB DF | Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Requested: Steam | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Steam | |
| Utility Material: Concrete | |
| Utility Color: Grey | |
| Nominal Utility Size: N/A | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: N/A | |
| Overall Width: N/A | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|--------------------------------------|
| Cover (Top) | Test Hole Profile Sketch: |
| 2.66 | |
| Cover (Bottom) | |
| 5.11' | |
| Drawn Facing | |
| NE | |
| Marker Set | |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

| | | |
|---|---|------------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: | Easting: | Elevation: |
| 686930.09 | 1578050.58 | 33.29 |
| Elevation Data: | | |
| Marker: 33.29' | Utility Top: 30.63' | Utility Bottom: 28.18' |
| Test Hole Notes: | | |
| Hub and tack set over eastern edge of steam duct. | | |
| | | |
| | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **59**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION



Point of Contact: Daniel Schriever, LS
 Phone Number: (443) 994-7285
 Date Performed: 12/21/2023
 Project Number: MD23-045
 Project Location: Perry Point, MD
 Requested By: AMT Engineering

CNC Civil Services


Project Name: PERRY POINT STEAM
UPDATE PROJECT

Utility Field Excavation Information

| | |
|--|--|
| Test Hole Number: 62 | Utility Condition: Poor <input type="checkbox"/> Fair <input checked="" type="checkbox"/> Good <input type="checkbox"/> See Notes <input type="checkbox"/> |
| Excavation Crew: KB AB DF | |
| Utility Requested: Unknown | Soil Condition: Clay <input type="checkbox"/> Sand <input checked="" type="checkbox"/> Rocks <input checked="" type="checkbox"/> Moist <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Hard <input type="checkbox"/> Soft <input checked="" type="checkbox"/> See Notes <input type="checkbox"/> |
| Utility Found: Unknown | |
| Utility Material: Direct Buried | |
| Utility Color: Black | |
| Nominal Utility Size: .5" (2) | Ground Type: Grass <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Asphalt <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Pavers <input type="checkbox"/> |
| O.D. Utility Size: .5" (2) | |
| Overall Width: 2" | |
| Utility Owner: Perry Point VA Hospital | Pavement Condition: Poor <input type="checkbox"/> Fair <input type="checkbox"/> Good <input type="checkbox"/> N/A <input checked="" type="checkbox"/> |
| Pavement Thickness: N/A (Grass) | |

| | |
|--|--------------------------------------|
| Cover (Top) | Test Hole Profile Sketch: |
| 1.66 | |
| Cover (Bottom) | |
| N/A' | |
| Drawn Facing | |
| NW | |
| Marker Set | |
| PK <input type="checkbox"/> | |
| Hub & Tack <input checked="" type="checkbox"/> | |
| Chis. "X" <input type="checkbox"/> | |

| | | |
|--|---|---------------------|
| Test Hole Survey Information: | | |
| Field Surveyed By: CNC Civil Services | Survey Control Established By: AMT Engineering | |
| Survey Coordinates: | | |
| Northing: | Easting: | Elevation: |
| 686870.17 | 1578012.19 | 31.99 |
| Elevation Data: | | |
| Marker: 31.99' | Utility Top: 30.33' | Utility Bottom: N/A |
| Test Hole Notes: | | |
| Hub and tack set over center of utility configuration. | | |
| | | |
| | | |



CNC Civil Services

CNC Civil Services, LLC
6856 Eastern Avenue - Suite 220
Washington, D.C. 20012

QL-A UTILITY PICTURE REPORT

Test Hole Number: **62**

PERRY POINT

Project Name: **TEST HOLES**

Project Number: **MD23-045**

Project Client: **AMT**

ORIGINAL SITE CONDITION



SITE RESTORATION CONDITION



TEST HOLE EXCAVATION OBSERVATION

